

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Pike Field Garage				PROJECT NO.	056756.256	
CLIENT	Radnor Township				DATE	11/21/2016	
Arrival Time Departure Time Total Hours	12:45 1:15 0.5 hrs	Weather: Site Condition: Temp Range:			⊠Hot □Warm □		
CONTRACTOR Torcon LABOR FORCE		SUBCONTRACTOR(S) JJD, Molly, High WORK PERFORMED					
Superintendent Foreman Operators Laborers Drivers		Avenue and Lan	ck is onsite cleanin ncaster Avenue) of ues on façade of pa	tire tracks ar	nd minor sediment/del	ust north of Pike Garage(Ithan bris.	
EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other	1						
SKETCH					COMMENTS		
				INSP	ECTOR:		
					rusko - Gannett Flemi	ng	