

PROJECT Villanova University - Pike Field Garage	PROJECT NO. 056756.256
CLIENT Radnor Township	DATE 11/23/2016

Arrival Time <u>11:45</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input checked="" type="checkbox"/> Hot <input type="checkbox"/> Warm <input type="checkbox"/> Cool <input checked="" type="checkbox"/> Cold
Departure Time <u>12:15</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>0.5 hrs</u>	Temp Range: <u>34°F</u> to <u>48°F</u>

CONTRACTOR Torcon	SUBCONTRACTOR(S) JJD, Molly, Reilly
--------------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent _____ Foreman _____ Operators _____ Laborers _____ Drivers _____	1) Sweeper Truck is onsite cleaning roadways and area of worksite just north of Pike Garage(Ithan Avenue and Lancaster Avenue) of tire tracks and minor sediment/debris. 2) A 2-man crew was laying out and installing the fence north of the athletic fields on the south side of Lancaster Avenue.
EQUIPMENT USED: Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
INSPECTOR: M. Prusko - Gannett Fleming	