Gannett Fleming

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - WLA Parking Lot	**PROJECT NO.**	056756.249
CLIENT	Radnor Twsp.	**DATE**	04/02/2016

Arrival Time	9:00a	Weather:	☐Clear ☒Overcast ☒Rain ☐Hot ☒Warm ☐Cool ☐Cold
Departure Time	10:00a	Site Condition:	☐Clear ☒Muddy ☐ Dusty ☒Wet ☐Snow ☐Ice ☐Foggy
Total Hours	1.0		
		Temp Range:	67°F to 48°F

CONTRACTOR Torcon

SUBCONTRACTOR(S) JJD, DBA, Brightline

LABOR FORCE

Superintendent	1
Foreman	1
Operators	2
Laborers	0
Drivers	0

EQUIPMENT USED:

Excavator	4
FEL	1
Dump Truck	3
Backhoe	2
Hoe Pac	
Vibratory Roller	2
Motorized Tamper	
Other	
Large Roller	1
Bulldozer	2
Lull	

WORK PERFORMED

1.) No one was onsite today upon my arrival. I had not been notified of this change in the work schedule through any communication from Torcon. The contractor had previously indicated that work was scheduled for today in an email dated March 31, 2016.
2.) I walked the entire site to check on all installed E&S controls which all appear functional at this time.

SKETCH

COMMENTS

1.) 9:00-10:00 = 1.0 Hours

INSPECTOR:
Jason Thompson - Gannett Fleming