

## **INSPECTOR'S DAILY REPORT**

PROJECT	Villanova	University - WLA Parking Lot	PROJECT NO.	056756.249	
CLIENT	Radnor Twsp.			DATE	05/02/2016
Arrival Time Departure Time Total Hours	8:30a 11:00a 2.5	Site Condition: ☐Clear ☑Mud  Temp Range: 70°F to 52°F	dy 🔲 Dusty	☐Hot ⊠Warm ☐	□Ice □Foggy
CONTRACTOR Torcon		T			JJD, DBA, Brightline, Roma
LABOR FORCE		WORK PERFORMED  1.) John Hosbach (Rockwell) and Bob (Rockwell) were onsite to do a walk-thru with Villanova and			
Superintendent Foreman Operators Laborers Drivers  EQUIPMEN  Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamp Other Large Roller Bulldozer Lull	4 1 3 2	Torcon concerning the plantings d 2.) I walked the entire site to check time. 3.) The stone face on the retaining retaining wall and the small section	one within the con all install wall continued used to be grading todate the proposed	ne "Buffer Zone".  Iled E&S controls where today. This is very sed to cover it.  It is get more areas und blacktop to be insta	nich all appear functional at this y slow work due to the size of the up to grade so that they may install alled.
	S	KETCH		CO	MMENTS
			2.) DB cylindo		n compaction and taking test