

PROJECT Villanova University - WLA Parking Lot	PROJECT NO. 056756.249
CLIENT Radnor Twsp.	DATE 05/06/2016

Arrival Time 11:00a	Weather: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Overcast <input checked="" type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time 12:00p	Site Condition: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours 1.0	Temp Range: 52°F to 46°F

CONTRACTOR Torcon	SUBCONTRACTOR(S) JJD, DBA, Brightline, Roma
--------------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent 1 Foreman 1 Operators 2 Laborers 0 Drivers 1	1.) Upon my arrival there did not appear to be any site work being conducted and it appears that all workers were no longer onsite. 2.) I walked the entire site to check on all installed E&S controls which all appear functional at this time. 3.) It appears that the base paving is almost completed at this time. All areas were paved with the exception of the area up front around the Construction Entrance.
EQUIPMENT USED:	
Excavator 4 FEL 1 Dump Truck 3 Backhoe 2 Hoe Pac _____ Vibratory Roller 2 Motorized Tamper _____ Other _____ Large Roller 1 Bulldozer 2 Lull _____	

SKETCH	COMMENTS
	INSPECTOR: Jason Thompson - Gannett Fleming