

| | |
|---|-------------------------------|
| PROJECT Villanova University - Pike Field Garage | PROJECT NO. 056756.256 |
| CLIENT Radnor Twsp. | DATE 05/16/2016 |

| | |
|------------------------------|--|
| Arrival Time <u>11:00a</u> | Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input checked="" type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold |
| Departure Time <u>11:30a</u> | Site Condition: <input type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy |
| Total Hours <u>0.5</u> | Temp Range: <u>67°F</u> to <u>42°F</u> |

| | |
|--------------------------|-----------------------------|
| CONTRACTOR Torcon | SUBCONTRACTOR(S) JJD |
|--------------------------|-----------------------------|

| LABOR FORCE | WORK PERFORMED |
|--|--|
| Superintendent <u>1</u> Foreman <u>1</u> Operators <u>2</u> Laborers <u>0</u> Drivers <u>1</u> | 1) Crews continued to work on stone façade of the retaining wall. 2) Doug (Torcon) informed me that removal of dirt stockpiles is planned to continue today. 3) A sweeper truck was onsite to address any debris/dirt accumulations along the Church Walk Driveway to Lancaster Avenue. Doug (Torcon) confirmed that the sweeper truck would remain onsite all day to keep the roadways clean. |
| EQUIPMENT USED: Excavator <u>4</u> FEL <u>1</u> Dump Truck <u>3</u> Backhoe <u>2</u> Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ Large Roller _____ Bulldozer _____ Lull _____ | |

| SKETCH | COMMENTS |
|--|----------|
| | |
| INSPECTOR: M. Prusko - Gannett Fleming | |