

<b>PROJECT</b>	<u>Villanova University - WLA Parking Lot</u>	<b>PROJECT NO.</b>	<u>056756.249</u>
<b>CLIENT</b>	<u>Radnor Twsp.</u>	<b>DATE</b>	<u>06/14/2016</u>

Arrival Time	<u>7:30a</u>	Weather:	<input type="checkbox"/> Clear	<input type="checkbox"/> Overcast	<input type="checkbox"/> Rain	<input type="checkbox"/> Hot	<input checked="" type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	<u>8:30a</u>	Site Condition:	<input type="checkbox"/> Clear	<input type="checkbox"/> Muddy	<input checked="" type="checkbox"/> Dusty	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	<u>1.0</u>	Temp Range:	<u>81°F to 55°F</u>						

<b>CONTRACTOR</b>	<u>Torcon</u>	<b>SUBCONTRACTOR(S)</b>	<u>JJD, DBA, Brightline, Roma</u>
-------------------	---------------	-------------------------	-----------------------------------

<b>LABOR FORCE</b>		<b>WORK PERFORMED</b>
Superintendent	<u>1</u>	1.) Stone face work continues on the retaining wall as well as the stairs/ramp by the work trailer. 2.) JJD continues with the grading for the proposed sidewalks along Lancaster Ave. and between the existing VU Halls onsite. 3.) Mayfield Gardens finished up cutting the grass in the restored areas and tree protection areas.
Foreman	<u>1</u>	
Operators	<u>2</u>	
Laborers	<u>0</u>	
Drivers	<u>1</u>	
<b>EQUIPMENT USED:</b>		
Excavator	<u>4</u>	
FEL	<u>1</u>	
Dump Truck	<u>3</u>	
Backhoe	<u>2</u>	
Hoe Pac	<u>          </u>	
Vibratory Roller	<u>2</u>	
Motorized Tamper	<u>          </u>	
Other	<u>          </u>	
Large Roller	<u>1</u>	
Bulldozer	<u>2</u>	
Lull	<u>          </u>	

<b>SKETCH</b>	<b>COMMENTS</b>
	1.) Site Times: 7:30-8:30 = 1.0 Hours
	<b>INSPECTOR:</b> <u>Jason Thompson - Gannett Fleming</u>