

## **INSPECTOR'S DAILY REPORT**

| PROJECT  | Villanova University - WLA Parking Lot                 |  |  | PROJECT NO.  | 056756.249                                   |
|--|--|--|--|--|--|
| CLIENT   | Radnor Twsp.   |  |  | DATE   | 06/21/2016                                   |
| Arrival Time Departure Time Total Hours  | 9:30a<br>3:30p<br>1.5                                  | Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Wet ☐ Snow ☐ Ice ☐ Foggy  Temp Range: 93°F to 70°F   |  |  |  |
| CONTRACTOR Torcon  LABOR FORCE   |  | 1  | SUBCONTRACTOR(S) JJD, DBA, Brightline, Roma WORK PERFORMED                                 |  |  |
| Superintendent Foreman Operators Laborers Drivers  EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampo Other Large Roller Bulldozer Lull | 1<br>2<br>0<br>1<br><b>T USED:</b><br>4<br>1<br>3<br>2 | 1.) Stone face work continues or 2.) JJD continues with the gradinexisting VU Halls onsite. 3.) Mayfield Gardens working o 4.) Roma Concrete continues to 5.) Davey Tree onsite tending to 6.) Mayfield Gardens tending to | n the retaining<br>ng for the prop<br>n the small reta<br>form and pour<br>existing trees. | wall. osed sidewalks along aining wall along the considewalk along Lanca | curbline behind Geraghty Hall.<br>aster Ave. |
|  | S  | KETCH  |  | COM  | MENTS  |
|  |  |  | INSP   | ECTOR:  n Thompson - Gannett   | 3:00-3:30 = 1.5 Hours                        |