

INSPECTOR'S DAILY REPORT

wsp.		0.1/22/2011
		DATE 06/22/2016
Arrival Time 7:30a Weather: Clear Overcast Rain Hot Warm Cool Cold Departure Time 3:30p Site Condition: Clear Muddy Dusty Wet Snow Ice Foggy Total Hours 4.5 Temp Range: 86°F to 66°F CONTRACTOR Torcon SUBCONTRACTOR(S) JJD, Cook Drilling, Molly		
WORK PERFORMED		
Superintendent 1 Foreman 0 Operators 1 Laborers 1 Drivers 0 0 Operators 1 Caborers 1 Operators 0 Operators		
КЕТСН		COMMENTS
	cylinde 2.) Site Hours.	te Times: 7:30-8:30, 10:00-12:00, 2:00-3:30 = 4.5
	Temp Range: 86°F to 66°F 1.) I walked the entire site to check time. 2.) Molly Construction continues various 3.) Sweeper truck onsite all day. 4.) JJD installed 26' of 18" HDPE (316) (26' of 18" HDPE @ 0.5%). 5.) Water truck used for dust control of the continued with excavation electric. 7.) JJD installed the proposed outled the proposed outled the proposed rule with the proposed rule in the proposed r	Temp Range: 86°F to 66°F SUBCON