

## **INSPECTOR'S DAILY REPORT**

PROJECT	Villanova University - WLA Parking Lot			PROJECT NO.	056756.249
CLIENT	Radnor Tv	vsp.		DATE	06/23/2016
Arrival Time Departure Time Total Hours	8:00a 3:30p 1.5	Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Wet ☐ Snow ☐ Ice ☐ Foggy  Temp Range: 86°F to 66°F			
CONTRACTOR Torcon					
Superintendent Foreman Operators Laborers Drivers  EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer Lull	1 2 0 1 T USED: 4 1 3 2	1.) Stone face work continues on (2.) JJD continues with the grading existing VU Halls onsite. 3.) Mayfiled Gardens completed t 4.) Mayfield Gardens continues to 5.) Mayfiled Gardens began restor were removed and restoration was 6.) Roma Concrete formed and pothe east side of Geraghty Hall. The sections of curb/sidewalk then for	the retaining of for the property of the small retain install plantication within a performed. For each of the curb ey also worked	ning wall along the coungs throughout the sit the tree protection are at the proposed entraced on repairs today by	curbline behind Geraghty Hall. ite. eas. First the chain link fences ance off of Lancaster Ave. along
	G)			G01	
	Si	KETCH		ECTOR:	MMENTS :00-3:30 = 1.5 Hours
				ECTOR: Thompson - Gannett	t Fleming