

PROJECT Villanova Parking Lot - WLA Parking Lot	PROJECT NO. 056756.249
CLIENT Radnor Township	DATE 06/27/2016

Arrival Time	<u>11:00</u>	Weather:	<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Overcast	<input type="checkbox"/> Rain	<input checked="" type="checkbox"/> Hot	<input type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	<u>1:00</u>	Site Condition:	<input type="checkbox"/> Clear	<input type="checkbox"/> Muddy	<input checked="" type="checkbox"/> Dusty	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	<u>2hrs</u>	Temp Range:	<u>69°F to 83°F</u>						

CONTRACTOR JJD	SUBCONTRACTOR(S) Mayfield Gardens
-----------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u>	1) Arrived onsite for required construction observation services and general site inspections. 2) Mayfield Gardens is onsite grading and seeding grass areas as well as planting trees and shrubs. 3) Contractor is onsite grading new parking lot entrance off of Lancaster Avenue. 4) I walked site to inspect E&S controls and found no problems or hazards within the installed controls. All of the inspected E&S controls appear to be in place, intact and operational as per the approved plans. 5) Sweeper truck is onsite keeping roadways and parking areas clear of any site dirt and debris.
Foreman <u>1</u>	
Operators <u>4</u>	
Laborers <u>8</u>	
Drivers <u>1</u>	
EQUIPMENT USED:	
Excavator <u>2</u>	
FEL _____	
Dump Truck _____	
Backhoe <u>1</u>	
Hoe Pac _____	
Vibratory Roller _____	
Motorized Tamper _____	
Other _____	
Bull Dozer <u>1</u>	
Sweeper Truck <u>1</u>	

SKETCH	COMMENTS
	INSPECTOR: Brandon Shirey