

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - WLA Parking Lot				PROJECT NO.	056756.249
CLIENT	Radnor Twsp.				DATE	07/12/2016
Arrival Time Departure Time Total Hours	7:30a 11:30a 2.0	Site Condition: Temp Range:		dy 🛭 Dusty	Hot □Warm □ Wet □Snow	□Ice □Foggy
CONTRACTOR Torcon LABOR FORCE		SUBCONTRACTOR(S) JJD, DBA, Brightline, Roma WORK PERFORMED				
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer Lull	1 2 0 1 T USED: 4 1 3 2	2.) HB Frazier collighting that has 3.) Mayfield Garneeded for moist 4.) Mayfield Gar	ontinued to install been connected unders continues te ture retention.	install planti the proposed p to this poin nding to prev ling seed and	ngs through out the I lighting along Lan- t. iously installed plar	site. caster Ave. as well as testing all ntings with water and mulch where graded topsoil through out the site
	S]	KETCH			CO	OMMENTS
				INSP	ECTOR:	0:30-11:30 - 2.0 Hours
				Jason	Thompson - Ganne	tt Fleming