

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - WLA Parking Lot			PROJECT NO.	056756.249
CLIENT	IENT Radnor Twsp.			DATE	07/13/2016
Arrival Time Departure Time Total Hours	10:30a 11:30a 1.0	Weather: ☐ Clear ☐ Overcast ☐ Rain ☐ Hot ☐ Warm ☐ Cool ☐ Cold Site Condition: ☐ Clear ☐ Muddy ☐ Dusty ☐ Wet ☐ Snow ☐ Ice ☐ Foggy Temp Range: 82°F to 72°F			
CONTRACTOR Torcon		ı	SUBCON	TRACTOR(S) JJI	D, DBA, Brightline, Roma
LABOR FORCE		WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Large Roller Bulldozer	4 1 3 2	JJD beagn the layout for the p Anyfield Gardens continues to needed for moisture retention. Mayfield Gardens continued is site behind all curbed areas for residue to the period of the p	ending to prev	viously installed planting	gs with water and mulch where
Lull					
SKETCH				COMMENTS	
				ECTOR: n Thompson - Gannett F	Reming