

PROJECT	<u>Villanova University - WLA Parking Lot</u>	PROJECT NO.	<u>056756.249</u>
CLIENT	<u>Radnor Twsp.</u>	DATE	<u>07/18/2016</u>

Arrival Time <u>8:00a</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input checked="" type="checkbox"/> Hot <input type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>1:30p</u>	Site Condition: <input type="checkbox"/> Clear <input type="checkbox"/> Muddy <input checked="" type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>1.0</u>	Temp Range: <u>93°F to 70°F</u>

CONTRACTOR <u>Torcon</u>	SUBCONTRACTOR(S) <u>JJD, DBA, Brightline, Roma</u>
---------------------------------	---

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>1</u> Operators <u>2</u> Laborers <u>0</u> Drivers <u>1</u>	1.) Mayfield Gardens continues tending to previously installed plantings with water and mulch where needed for moisture retention. 2.) No other site work was performed today.
EQUIPMENT USED:	
Excavator <u>4</u> FEL <u>1</u> Dump Truck <u>3</u> Backhoe <u>2</u> Hoe Pac <u> </u> Vibratory Roller <u>2</u> Motorized Tamper <u> </u> Other <u> </u> Large Roller <u>1</u> Bulldozer <u>2</u> Lull <u> </u>	

SKETCH	COMMENTS
--------	----------

	1.) Site Times: 8:00-8:30, 1:00-1:30 - 1.0 Hour
--	---

	INSPECTOR: <u>Jason Thompson - Gannett Fleming</u>
--	--