

<b>PROJECT</b>	<u>Villanova University - WLA Parking Lot</u>	<b>PROJECT NO.</b>	<u>056756.249</u>
<b>CLIENT</b>	<u>Radnor Twsp.</u>	<b>DATE</b>	<u>07/19/2016</u>

Arrival Time	<u>12:30a</u>	Weather:	<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Overcast	<input type="checkbox"/> Rain	<input checked="" type="checkbox"/> Hot	<input type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	<u>1:30p</u>	Site Condition:	<input type="checkbox"/> Clear	<input type="checkbox"/> Muddy	<input checked="" type="checkbox"/> Dusty	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	<u>1.0</u>	Temp Range:	<u>86°F to 64°F</u>						

<b>CONTRACTOR</b>	<u>Torcon</u>	<b>SUBCONTRACTOR(S)</b>	<u>JJD, DBA, Brightline, Roma</u>
-------------------	---------------	-------------------------	-----------------------------------

LABOR FORCE	WORK PERFORMED		
Superintendent	<u>1</u>	1.) Mayfield Gardens continues tending to previously installed plantings with water and mulch where needed for moisture retention. 2.) Mayfield Gardens continued installing seed and straw matting over graded topsoil throughout the site behind all curbed areas for restoration. 3.) Surveyor onsite performing as-built survey. 4.) No other site work was performed today.	
Foreman	<u>1</u>		
Operators	<u>2</u>		
Laborers	<u>0</u>		
Drivers	<u>1</u>		
EQUIPMENT USED:			
Excavator	<u>4</u>		
FEL	<u>1</u>		
Dump Truck	<u>3</u>		
Backhoe	<u>2</u>		
Hoe Pac	<u>    </u>		
Vibratory Roller	<u>2</u>		
Motorized Tamper	<u>    </u>		
Other	<u>    </u>		
Large Roller	<u>1</u>		
Bulldozer	<u>2</u>		
Lull	<u>    </u>		

SKETCH	COMMENTS
	1.) Site Times: 9:30-10:30, 1:30-2:30 - 2.0 Hours
	<b>INSPECTOR:</b> <u>Jason Thompson - Gannett Fleming</u>