

<b>PROJECT</b> Villanova University - WLA Parking Lot	<b>PROJECT NO.</b> 056756.249
<b>CLIENT</b> Radnor Township	<b>DATE</b> 07/22/2016

Arrival Time 8:00	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input checked="" type="checkbox"/> Hot <input type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time 8:30	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours .5hrs	Temp Range: 73°F to 94°F

<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b> JJD, DBA, Brightline, Roma
--------------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent 1	1) Arrived onsite for required construction observation services and general site inspections.  2) Mayfield gardens is mulching and watering around plantings previously installed onsite aswell as grading of grass areas along rt 30.  3) Peco is working along roadway on rt 30.  4) There is no other site work being performed today.
Foreman 1	
Operators 2	
Laborers 3	
Drivers 1	
<b>EQUIPMENT USED:</b>	
Excavator 2	
FEL 1	
Dump Truck 2	
Backhoe 1	
Hoe Pac _____	
Vibratory Roller _____	
Motorized Tamper _____	
Other _____	
_____	
_____	
_____	

SKETCH	COMMENTS
	<b>INSPECTOR:</b> Brandon Shirey - Gannett Fleming