

PROJECT	<u>Villanova University - WLA Parking Lot</u>	PROJECT NO.	<u>056756.249</u>
CLIENT	<u>Radnor Township</u>	DATE	<u>07/25/2016</u>

Arrival Time	<u>10:00</u>	Weather:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Overcast	<input checked="" type="checkbox"/> Rain	<input checked="" type="checkbox"/> Hot	<input type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	<u>10:30</u>	Site Condition:	<input type="checkbox"/> Clear	<input checked="" type="checkbox"/> Muddy	<input type="checkbox"/> Dusty	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	<u>.5hrs</u>	Temp Range:	<u>74°F to 97°F</u>						

CONTRACTOR <u>Torcon</u>	SUBCONTRACTOR(S) <u>JJD, DBA, Brightline, Roma</u>
---------------------------------	---

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>1</u> Operators <u>2</u> Laborers <u>3</u> Drivers <u>1</u>	1) Arrived onsite for required construction observation services and general site inspections. 2) Mayfield gardens is mulching and watering around plantings previously installed onsite aswell as grading of grass areas along Rt. 30. 3) There is no other site work being performed today. 4) E&S controls installed onsite appear in place and operational per the approved plans.
EQUIPMENT USED: Excavator <u>2</u> FEL <u>1</u> Dump Truck <u>2</u> Backhoe <u>1</u> Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
	INSPECTOR: <u>Brandon Shirey - Gannett Fleming</u>