

INSPECTOR'S DAILY REPORT

PROJECT Villanova University - WLA Parking Lot			PROJECT NO. 056756.249		
CLIENT Radnor Township			DATE 08/05/2016		
9:00 12:30 1hr					
Torcon		SUBCON	NTRACTOR(S) JJD, DBA, Brightline, Ror	na	
LABOR FORCE			WORK PERFORMED		
1 1 3 8 3	 Arrived onsite for required construction observation services and general site inspections. Kehoe is onsite installing the asphalt wearing course from new entrance off of Lancaster Avenue up to the first parking lot area behind stone retaining wall. E&S controls around site all appear to be in place and operational as per the approved plans. 				
1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	4) Work to continue in the morning	g.			
S]	КЕТСН		COMMENTS		
		INSP	PECTOR:		
	9:00 12:30 1hr Torcon RCE 1 1 3 8 3 USED: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Site Condition: Clear Over Over 12:30 Site Condition: Clear Mud Mud Temp Range: 68°F to 85°F	Sketch S	Radnor Township	