

PROJECT Villanova University - WLA Parking Lot		PROJECT NO. 056756.249
CLIENT Radnor Township		DATE 08/10/2016
Arrival Time <u>11:30</u>	Weather: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Overcast <input type="checkbox"/> Rain <input checked="" type="checkbox"/> Hot <input type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold	
Departure Time <u>3:00</u>	Site Condition: <input type="checkbox"/> Clear <input type="checkbox"/> Muddy <input checked="" type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy	
Total Hours <u>1.5hrs</u>	Temp Range: <u>76°F</u> to <u>91°F</u>	
CONTRACTOR Torcon		SUBCONTRACTOR(S) JJD, DBA, Brightline, Roma
LABOR FORCE		WORK PERFORMED
Superintendent <u>1</u>		1) Arrived onsite for required construction observation services and general site inspections. 2) Kehoe is onsite painting all of the required lines on the asphalt for traffic control and parking spaces as described within the approved site plans.
Foreman <u>1</u>		
Operators <u>3</u>		
Laborers <u>8</u>		
Drivers <u>3</u>		
EQUIPMENT USED:		
Excavator <u>1</u>		
FEL _____		
Dump Truck <u>3</u>		
Backhoe _____		
Hoe Pac _____		
Vibratory Roller <u>1</u>		
Motorized Tamper _____		
Other _____		
Paving Machine <u>1</u>		

SKETCH		COMMENTS
		1) Left site at 12:30am and returned at 2:30pm.
		INSPECTOR: Brandon Shirey - Gannett Fleming