

<b>PROJECT</b> Villanova University - WLA Parking Lot	<b>PROJECT NO.</b> 056756.249
<b>CLIENT</b> Radnor Township	<b>DATE</b> 08/11/2016
Arrival Time <u>11:00</u> Weather: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Overcast <input checked="" type="checkbox"/> Rain <input checked="" type="checkbox"/> Hot <input type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold Departure Time <u>3:00</u> Site Condition: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy Total Hours <u>2hrs</u> Temp Range: <u>77°</u> F to <u>91°</u> F	
<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b> JJD, Brightline, Roma, Meco
<b>LABOR FORCE</b>	<b>WORK PERFORMED</b>
Superintendent <u>1</u> Foreman <u>1</u> Operators <u>2</u> Laborers <u>3</u> Drivers <u>2</u>	1) Arrived onsite for required construction observation services and general site inspections.  2) Meco construction is onsite removing the old existing sidewalk along Lancaster Avenue on the east side of the site in the existing parking lot area.  3) A site inspection of installed E&S controls found no problems or issues within the controls onsite. Everything appears to be in place and operational per the approved site plans.  4) JJD is grading and prepping the new entrance to the parking lot off of Lancaster Avenue.
<b>EQUIPMENT USED:</b>	
Excavator <u>2</u> FEL _____ Dump Truck <u>2</u> Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	
<b>SKETCH</b>	<b>COMMENTS</b>
	1) Left site at 12:00pm and returned at 2:00pm.
	<b>INSPECTOR:</b> Brandon Shirey - Gannett Fleming