

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - WLA Parking Lot			PROJECT NO.	056756.249
CLIENT	Radnor To	Radnor Township			09/08/2016
Arrival Time Departure Time Total Hours	11:00 3:00 2hrs	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy Temp Range: 71°F to 95°F			
CONTRACTOR Torcon			SUBCON	TRACTOR(S)	JJD, Brightline, Kehoe, Meco
LABOR FORCE		WORK PERFORMED			
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other		Arrived onsite for required cor Roma concrete onsite pouring Walk and Moriarty Hall. Mayfield Gardens onsite tending	sidewalks in f	front of staircase alor	ng Lancaster Ave between Church
	SI	LKETCH		CO	MMENTS
			INSP	t site at 12:00pm and ECTOR: don Shirey - Gannett	t Eleming
			- Diuli		