

<b>PROJECT</b> Villanova University - WLA Parking Lot	<b>PROJECT NO.</b> 056756.249
<b>CLIENT</b> Radnor Township	<b>DATE</b> 09/13/2016

Arrival Time	7:00	Weather:	<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Overcast	<input type="checkbox"/> Rain	<input type="checkbox"/> Hot	<input checked="" type="checkbox"/> Warm	<input type="checkbox"/> Cool	<input type="checkbox"/> Cold
Departure Time	9:00	Site Condition:	<input type="checkbox"/> Clear	<input type="checkbox"/> Muddy	<input checked="" type="checkbox"/> Dusty	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow	<input type="checkbox"/> Ice	<input type="checkbox"/> Foggy
Total Hours	2hrs	Temp Range:	63°F to 83°F						

<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b> JJD, Brightline, Kehoe, Meco
--------------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u>	1) Arrived onsite for required construction observation services and general site inspections.  2) Roma concrete onsite pouring sidewalk sections in front of staircase adjacent to Church Walk along Lancaster Ave and in front of Moriarty Hall along Lancaster Ave.  3) Sweeper truck onsite to clean roadways and parking areas around site.  4) Water truck onsite for dust control.
Foreman <u>1</u>	
Operators _____	
Laborers <u>6</u>	
Drivers _____	
<b>EQUIPMENT USED:</b>	
Excavator _____	
FEL _____	
Dump Truck _____	
Backhoe _____	
Hoe Pac _____	
Vibratory Roller _____	
Motorized Tamper _____	
Other _____	
_____	
_____	
_____	

SKETCH	COMMENTS
	<b>INSPECTOR:</b> Brandon Shirey - Gannett Fleming