

<b>PROJECT</b> Villanova University - WLA Parking Lot	<b>PROJECT NO.</b> 056756.249
<b>CLIENT</b> Radnor Township	<b>DATE</b> 09/15/2016

Arrival Time 10:00	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time 10:30	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours .5hrs	Temp Range: 54°F to 75°F

<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b> JJD, Brightline, Meco, Roma
--------------------------	---

<b>LABOR FORCE</b>	<b>WORK PERFORMED</b>
Superintendent 1	1) Arrived onsite for required construction observation services and general site inspections.  2) Meco construction is onsite spreading topsoil and seeding grass areas around staircase between Church Walk and Moriarty Hall.  3) Sweeper truck onsite to clean roadways and parking areas around site.  4) Water truck onsite for dust control.  5) Mayfield Gardens is onsite planting trees in front of Moriarty Hall and tending to previous plantings around site.
Foreman 1	
Operators 1	
Laborers 6	
Drivers 2	
<b>EQUIPMENT USED:</b>	
Excavator _____	
FEL _____	
Dump Truck 2	
Backhoe _____	
Hoe Pac _____	
Vibratory Roller 1	
Motorized Tamper _____	
Other _____	
Gradall 1	
_____	
_____	

<b>SKETCH</b>	<b>COMMENTS</b>
	<b>INSPECTOR:</b> Brandon Shirey - Gannett Fleming