

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - WLA Parking Lot				PROJECT NO.	056756.249	
CLIENT	Radnor To	dnor Township			DATE	09/20/2016	
Arrival Time Departure Time Total Hours	10:00 11:30 1.5	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy Temp Range: 63°F to 82°F					
CONTRACTOR Torcon				SUBCON	TRACTOR(S)	JJD, Brightline, Meco, Roma	
LABOR FO	ORCE	WORK PERFORMED					
Superintendent Foreman Operators Laborers Drivers	1 1 3 6 4	 Arrived onsite for required construction observation services and general site inspections. Meco construction is installing the wearing course for the proposed turning lanes and entrance to the new parking lot off of Lancaster Ave adjacent to Moriarty Hall. Sweeper truck onsite to clean roadways and parking areas around site. 					
EQUIPMENT	USED:]					
Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tampe Other Gradall Paving Machine Skid Steer	2 1 1 1 1 1 1						
SKETCH					COMMENTS		
					ECTOR: lon Shirey - Gannet	tt Fleming	