

## **INSPECTOR'S DAILY REPORT**

PROJECT V	Villanova University - WLA Parking Lot				PROJECT NO.	056756.249
CLIENT R	Radnor Township				DATE	09/23/2016
Departure Time 1	.5 hrs	Weather:   Clear   Overcast   Rain   Hot   Warm   Cool   Cold   Site Condition:   Clear   Muddy   Dusty   Wet   Snow   Ice   Foggy   Temp Range:   60°F to 87°F				
CONTRACTOR Torcon		SUBCONTRACTOR(S) JJD, Meco, Mayfield				
LABOR FORCE		WORK PERFORMED				
Superintendent Foreman Operators Laborers Drivers  EQUIPMENT U Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other Gradall Paving Machine Skid Steer	1 2 6 3 2 t	2) Meco onsite i of Moriarty Hall 3) Mayfield onsi 4) Torcon Foren two	nstalling temporar . Temporart walk- ite to stabilize new nan informed me t	ry walkway a way hot-mix vly graded are hat new traffi	asphalt tamped into pla eas north of Moriarty H	hurch Walk Driveway just east ace with plate tamping machine Iall and near Visitor Lot rive onsite in the next week or
	I SKI	ЕТСН			COM	MENTS
				2) Stev	Hosbach onsite (Rocker Norcini onsite (Radner Norcini onsite (Rocker Norcini onsite (Radner	nor)