

<b>PROJECT</b> Villanova University - WLA Parking Lot	<b>PROJECT NO.</b> 056756.249
<b>CLIENT</b> Radnor Township	<b>DATE</b> 10/03/2016

Arrival Time <u>12:30</u>	Weather: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>1:00</u>	Site Condition: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>.5</u>	Temp Range: <u>54°F</u> to <u>73°F</u>

<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b>
--------------------------	-------------------------

<b>LABOR FORCE</b>	<b>WORK PERFORMED</b>
Superintendent <u>1</u> Foreman <u>1</u> Operators _____ Laborers _____ Drivers _____	1) Arrived onsite for required construction observation services and general site inspections.  2) I performed an inspection of the E&S controls installed onsite. All of the inspected controls appear to be in place and operational per the approved plans.
<b>EQUIPMENT USED:</b> Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

<b>SKETCH</b>	<b>COMMENTS</b>
	<b>INSPECTOR:</b> Brandon Shirey - Gannett Fleming