

PROJECT Villanova University - WLA Parking Lot	PROJECT NO. 056756.249
CLIENT Radnor Township	DATE 10/05/2016

Arrival Time <u>11:00</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>12:00</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>1</u>	Temp Range: <u>55°F</u> to <u>71°F</u>

CONTRACTOR Torcon	SUBCONTRACTOR(S) Mayfield,JJD,Miller Bros
--------------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>1</u> Operators <u>2</u> Laborers <u>5</u> Drivers _____	1) Arrived onsite for required construction observation services and general site inspections. 2) Mayfield gardens tending to plantings in various locations around site. 3) JJD installing trash snouts inside the parking lot inlets. 4) Miller Bros are onsite installing new traffic signals for the Church Walk intersection.
EQUIPMENT USED: Excavator _____ FEL _____ Dump Truck _____ Backhoe <u>2</u> Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
	INSPECTOR: Brandon Shirey - Gannett Fleming