

<b>PROJECT</b> Villanova University - WLA Parking Lot	<b>PROJECT NO.</b> 056756.249
<b>CLIENT</b> Radnor Township	<b>DATE</b> 10/13/2016

Arrival Time 12:00	Weather: <input type="checkbox"/> Clear <input checked="" type="checkbox"/> Overcast <input checked="" type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time 12:30	Site Condition: <input type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours .5	Temp Range: 43°F to 68°F

<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b> Miller Bros
--------------------------	-------------------------------------

LABOR FORCE	WORK PERFORMED
Superintendent 1 Foreman 1 Operators _____ Laborers _____ Drivers _____	1) Arrived onsite for required construction observation services and general site inspections.  2) Miller Bros are onsite installing new traffic signals and making electrical connections for the Church Walk intersection.
<b>EQUIPMENT USED:</b>	
Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
<b>INSPECTOR:</b> Brandon Shirey - Gannett Fleming	