

PROJECT Villanova University - WLA Parking Lot	PROJECT NO. 056756.249
CLIENT Radnor Township	DATE 11/02/2016

Arrival Time <u>2:00</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>3:00</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>1</u>	Temp Range: <u>55°F</u> to <u>71°F</u>

CONTRACTOR Torcon	SUBCONTRACTOR(S) Mayfield
--------------------------	----------------------------------

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>1</u> Operators _____ Laborers <u>1</u> Drivers <u>1</u>	1) Arrived onsite for required construction observation services and general site inspections. 2) Mayfield gardens onsite tending to plantings with water and mulch. Support wires for select plantings are being removed along with the stakes holding them in place. 3) Walked site to inspect the installed E&S controls. All of the installed controls appear to be in place and operational per the approved plans.
EQUIPMENT USED:	
Excavator _____ FEL _____ Dump Truck <u>1</u> Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
	INSPECTOR: Brandon Shirey - Gannett Fleming