

PROJECT <u>Villanova University - Church Walk & Bridge</u>	PROJECT NO. <u>056756.272</u>
CLIENT <u>Radnor Township</u>	DATE <u>03/23/2017</u>

Arrival Time <u>10:00a</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input type="checkbox"/> Cool <input checked="" type="checkbox"/> Cold
Departure Time <u>11:30a</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>1.5 hrs</u>	Temp Range: <u>43°F</u> to <u>20°F</u>

CONTRACTOR <u>Torcon, Inc & Neshaminy, Constructors, Inc..</u>	SUBCONTRACTOR(S)
---	-------------------------

LABOR FORCE	WORK PERFORMED
Superintendent _____ Foreman _____ Operators _____ Laborers _____ Drivers _____	GF attended the weekly meeting with Neshamany Const. Inc., Torcon, and PennDOT to review operations and schedule for the next four weeks. During the meeting the E&S controls were discussed and determined that they would be installed late next week prior to tree removal.
EQUIPMENT USED: Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____	

SKETCH	COMMENTS
INSPECTOR: <u>William Wood-Jenkins - Gannett Fleming</u>	

