

<b>PROJECT</b> Villanova University - Pike Field Garage	<b>PROJECT NO.</b> 056756.256
<b>CLIENT</b> Radnor Township	<b>DATE</b> 01/04/2017

Arrival Time <u>7:15</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>8:00</u>	Site Condition: <input type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>0.75hrs</u>	Temp Range: <u>23°F</u> to <u>48°F</u>

<b>CONTRACTOR</b> Torcon	<b>SUBCONTRACTOR(S)</b>
--------------------------	-------------------------

LABOR FORCE	WORK PERFORMED
Superintendent _____ Foreman _____ Operators _____ Laborers _____ Drivers _____	1) Onsite to check for any E&S control issues due to the rainfall the previous day. Roadways (Lancaster Avenue and Ithan Avenue) appeared to be clear and there does not appear to be any evidence of silt or debris at this time. 2) Contractor has installed a chain-link fence around the perimeter of the future location of the PAC just north of Pike Garage. This area is to be used for construction vehicles and staging at this time. 3) JJD installed asphalt walking path along the south and east side of the garage structure. 4) The eastern most light along the fire access lane is still not installed at this time.
<b>EQUIPMENT USED:</b> Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
<b>INSPECTOR:</b> Matthew Prusko - Gannett Fleming	