

PROJECT <u>Villanova University - Lancaster Avenue Housing</u>	PROJECT NO. <u>056756.277</u>
CLIENT <u>Radnor Township</u>	DATE <u>01/12/2017</u>

Arrival Time <u>12:30</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input checked="" type="checkbox"/> Warm <input type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>1:00</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>0.5 hrs</u>	Temp Range: <u>44°F</u> to <u>64°F</u>

CONTRACTOR <u>Torcon</u>	SUBCONTRACTOR(S) <u>Mayfield Site, Federal Fence</u>
---------------------------------	---

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman _____ Operators _____ Laborers <u>2</u> Drivers _____	1) Federal Fence was onsite installing chain link fence along the perimeter of Main Lot.
EQUIPMENT USED:	
Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
INSPECTOR: <u>Matthew Prusko - Gannett Fleming</u>	