

PROJECT <u>Villanova University - Lancaster Avenue Housing</u>	PROJECT NO. <u>056756.256</u>
CLIENT <u>Radnor Township</u>	DATE <u>01/18/2017</u>

Arrival Time <u>1:15</u>	Weather: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Overcast <input type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time <u>1:45</u>	Site Condition: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours <u>0.5 hrs</u>	Temp Range: <u>36°F</u> to <u>45°F</u>

CONTRACTOR <u>Torcon</u>	SUBCONTRACTOR(S) <u>Molly, Mayfield Site Cont., Federal Fence</u>
---------------------------------	--

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u>	1) Federal Fence was onsite installing chain link fence along the perimeter of Main Lot. 2) Mayfield Site Cont. was onsite performing general site clean-up in preparation of the upcoming construction activities for this phase. 3) Tim (Torcon) informed MJP that the DCCD had performed a site visit the previous day to inspect the E&S measures that were being installed. Mayfield site Cont. was onsite stabilizing and stoning a few disturbed areas along Ithan Avenue.
Foreman <u>1</u>	
Operators <u>1</u>	
Laborers <u>6</u>	
Drivers _____	
EQUIPMENT USED:	
Excavator _____	
FEL <u>1</u>	
Dump Truck _____	
Backhoe _____	
Hoe Pac _____	
Vibratory Roller _____	
Motorized Tamper _____	
Other _____	

SKETCH	COMMENTS
	INSPECTOR: <u>Matthew Prusko - Gannett Fleming</u>

