

INSPECTOR'S DAILY REPORT

PROJECT _	Villanova University - Lancaster Avenue Housin				PROJECT NO.	056756.277	
CLIENT _	Radnor Township				DATE	02/02/2017	
_	6:30a 4:00p 9.5 hrs	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy Temp Range: 30°F to 44°F					
CONTRACTOR Torcon LABOR FORCE					CONTRACTOR(S) Mayfield Site Cont. ORK PERFORMED		
Superintendent Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other	1 2 4 7 USED:	foundation area dump trucks wh 2) Mayfield con set about 16' of clean 57 stone, a site. The contract 3) Starfire (subc	of the western mo nich are hauling the tinued excavating reinforced concret and the pipe was a ctor enclosed the v	ayfield) conti st proposed be material off for storm sev e pipe (RCP) lso encased in work area in n eld) has a stre	nued removing bulk so building. A large track- site. wer pipe from RG-203 at 0.05% slope. Pipe v in the stone. Excavation modular fencing at the	oil and materials for the thoe excavator is loading tri-axle toward MH-252. The contractor was set upon about 6 inches of a spoils were exported from the conclusion of the day. ly cleaning the lot and adjacent	
SKETCH					COMMENTS		
					ECTOR: iam Wood-Jenkins - G	annett Fleming	