

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Lancaster Avenue Housing				PROJECT NO.	056756.277
CLIENT	Radnor To	Radnor Township			DATE	02/13/2017
Arrival Time Departure Time Total Hours CONTRACTO		Site Condition: \square C Temp Range: 34° F		dy 🛛 Dusty	Hot Warm [Wet Snow TRACTOR(S)	
LABOR FO	1	WORK PERFORMED 1) Mayfield Site Construction (Mayfield) continued removing bulk soil and materials for the				
Foreman Operators Laborers Drivers EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamp Other	15	foundation area of the north-eastern portion of the west building. A large track-hoe excavator is loading tri-axle dump trucks which are hauling the material offsite. 2) Mayfield continued excavating for storm sewer pipe and structures from MH-250 toward RG-208. The contractor set about 60' of reinforced concrete pipe (RCP) at 0.05% slope toward RG-208. Pipe and structures were set upon about 6 inches of clean stone, the pipe was also encased in the stone. Excavation spoils were exported from the site. Trench backfill is comprised of imported tan 2A modified stone being placed in approximately 12" thick lifts and compacted with a walk along vibratory roller. The contractor backfilled the pipe set between MH-251 to MH-250 and toward RG-208. The contractor enclosed the work area in modular fencing at the conclusion of the day. 3) Starfire (subcon tract for Mayfield) has a street sweeper continuously cleaning the lot and adjacent roadways to manage dirt and dust issues. 4) Molly Concrete Contractors, Inc. began excavating for the building foundations in the western area of the west building. Excavation spoils are being loaded into tri-axle dump trucks and unloaded into a stockpile onsite and being maintained by a small dozer.				
	S	KETCH		COMMENTS		
				INSP	ECTOR:	- Gannett Fleming