

| | | | |
|----------------|--------------------------------------------------------|--------------------|-------------------|
| PROJECT | <u>Villanova University - Lancaster Avenue Housing</u> | PROJECT NO. | <u>056756.277</u> |
| CLIENT | <u>Radnor Township</u> | DATE | <u>02/27/2017</u> |

| | | | | | | | | | |
|----------------|----------------|-----------------|-------------------------------------------|-----------------------------------|-------------------------------------------|------------------------------|-------------------------------|------------------------------------------|--------------------------------|
| Arrival Time | <u>10:30a</u> | Weather: | <input checked="" type="checkbox"/> Clear | <input type="checkbox"/> Overcast | <input type="checkbox"/> Rain | <input type="checkbox"/> Hot | <input type="checkbox"/> Warm | <input checked="" type="checkbox"/> Cool | <input type="checkbox"/> Cold |
| Departure Time | <u>12:00p</u> | Site Condition: | <input checked="" type="checkbox"/> Clear | <input type="checkbox"/> Muddy | <input checked="" type="checkbox"/> Dusty | <input type="checkbox"/> Wet | <input type="checkbox"/> Snow | <input type="checkbox"/> Ice | <input type="checkbox"/> Foggy |
| Total Hours | <u>1.5 hrs</u> | Temp Range: | <u>24°F to 51°F</u> | | | | | | |

| | |
|---------------------------------------|----------------------------------------------------|
| CONTRACTOR <u>Torcon, Inc.</u> | SUBCONTRACTOR(S) <u>Mayfield Site Cont.</u> |
|---------------------------------------|----------------------------------------------------|

| LABOR FORCE | WORK PERFORMED |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Superintendent <u>1</u> Foreman <u>1</u> Operators _____ Laborers _____ Drivers _____ | Gannett Fleming made a visit to the site to confirm the activities onsite were as scheduled and to review the conditions of the surrounding roads. Site and foundation excavations continue, with soils being stockpiled onsite in protected areas. Concrete and masonry placement for the foundations in the wester half of the west building continue, with waste materials being disposed of in the prescribed dumpsters. Roadways around the site are observed to be clean and free of debris, no build up of mud/dirt; the street sweeper continues to make rounds through the site and perimeter roads. |
| EQUIPMENT USED: | |
| Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____ | |

| SKETCH | COMMENTS |
|---------------|----------------------------------------------------------------------------------------------|
| | 1 Technician from Geostrutures, Inc. and 1 technician from Advanced Geosystems onsite today. |
| | INSPECTOR: <u>William Wood-Jenkins - Gannett Fleming</u> |