

<b>PROJECT</b> Villanova University - Lancaster Avenue Housing	<b>PROJECT NO.</b> 056756.277
<b>CLIENT</b> Radnor Township	<b>DATE</b> 03/01/2017

Arrival Time	<u>10:15a</u>	Weather:	<input type="checkbox"/> Clear <input type="checkbox"/> Overcast <input checked="" type="checkbox"/> Rain <input type="checkbox"/> Hot <input type="checkbox"/> Warm <input checked="" type="checkbox"/> Cool <input type="checkbox"/> Cold
Departure Time	<u>11:15a</u>	Site Condition:	<input type="checkbox"/> Clear <input type="checkbox"/> Muddy <input type="checkbox"/> Dusty <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Snow <input type="checkbox"/> Ice <input type="checkbox"/> Foggy
Total Hours	<u>2 hrs</u>	Temp Range:	<u>48°F</u> to <u>73°F</u>

<b>CONTRACTOR</b> Torcon, Inc.	<b>SUBCONTRACTOR(S)</b> Mayfield Site Cont.
--------------------------------	---

LABOR FORCE	WORK PERFORMED
Superintendent <u>1</u> Foreman <u>1</u> Operators _____ Laborers _____ Drivers _____	Gannett Fleming made a visit to the site to confirm the activities onsite were as scheduled and to review the conditions of the roads. Site and foundation excavations continue, with soils being exported off site. Concrete and masonry placement for the foundations in the wester half of the west building continue. Roadways around the site are observed to be clean and free of debris, no build up of mud/dirt; the street sweeper continues to make rounds through the site and perimeter roads. E&S controls were observed being maintained with the rainy conditions.
<b>EQUIPMENT USED:</b>	
Excavator _____ FEL _____ Dump Truck _____ Backhoe _____ Hoe Pac _____ Vibratory Roller _____ Motorized Tamper _____ Other _____ _____ _____ _____	

SKETCH	COMMENTS
	1 Technician from Geostrutures, Inc. and 1 technician from Advanced Geosystems onsite today. Travel time between sites included.
	<b>INSPECTOR:</b> William Wood-Jenkins - Gannett Fleming