

INSPECTOR'S DAILY REPORT

PROJECT	Villanova	University - Lancaster Avenue F	Iousing	PROJECT NO.	056756.277
CLIENT	Radnor To	ownship		DATE	03/15/2017
Arrival Time Departure Time Total Hours	10:00a 12:00p 2 hrs	Site Condition: ☐Clear ☑Mud Temp Range: 18°F to 28°F	dy Dusty	Hot	
CONTRACTO		, Inc.		TRACTOR(S) Co	oncrete Cont., D.M. Sabia, Inc.
Foreman Operators Laborers Drivers EQUIPMENT USED: Excavator FEL half of the day and continued excal building. Large track-hoe excavate offsite. 2.) The street sweeper is continuou other debris issues. 3.) Molly Concrete Contractors, Ir clear off footings from the snowfar dear off the east building along Ithat side of the east		field) continued augering for steal beam posts along the eastern an Ave. Steal I-beam posts are being installed in concrete to protect the deep foundation excavations proposed for the area as part of ations.			
	S	KETCH		COM	MENTS
				ECTOR: iam Wood-Jenkins - Ga	nnett Fleming