

INSPECTOR'S DAILY REPORT

PROJECT	Villanova University - Lancaster Avenue Housing			PROJECT NO.	056756.277
CLIENT	Radnor Township			DATE	04/04/2017
Arrival Time Departure Time Total Hours	7:00a 3:00p 8 hrs	Weather: ☐Clear ☐Overcast ☐Rain ☐Hot ☐Warm ☐Cool ☐Cold Site Condition: ☐Clear ☐Muddy ☐ Dusty ☐Wet ☐Snow ☐Ice ☐Foggy Temp Range: 47°F to 74°F			
CONTRACTOR Torcon,		, Inc. SUBCON		TRACTOR(S) Mayfield Site Cont. Inc.	
Superintendent Foreman Operators Laborers Drivers	1 2 4 6 4	1.) Mayfield Site Construction (Mayfield) continued excavating for storm sewer from MH-222 to MH-201. Residual material was excavated from the area and placed in a tri-axle dump truck for export off site. The contractor set 2 lengths (about 28 ft.) of 36 inch diameter HDPE pipe at 0.005% grade. Pipe was set upon 6+ inches of 2B clean stone, also pipe was encased in the clean stone. 2.) Roadways around the site are observed to be clean and free of debris, no build up of mud/dirt. Mayfield subcontracted a street sweeper to constantly maintain the paved areas of the site and surrounding roadways. Additionally, the contractor is washing off truck tires prior to trucks departing the site.			
EQUIPMENT Excavator FEL Dump Truck Backhoe Hoe Pac Vibratory Roller Motorized Tamper Other	<u>3</u> <u>4</u>				
	SI	KETCH		COM	IMENTS
			INSPI	nician from Geostruct stems, Inc. were onsite stems, Inc. were onsite stems. ECTOR: am Wood-Jenkins - G	